# Environmental Considerations When Conducting Geothermal Feasibility Evaluations

Presented by: Don Maggioli, PE, LSP, CGD (Certified Geothermal Designer)

Alares LLC

248 Copeland Street

Quincy, MA 02169

617-995-4397

dmaggioli@AlaresLLC.com



# **Overview**

- 1. Why Evaluate Environmental Site Conditions
- 2. How Does One Evaluate Environmental Conditions
- 3. Case Study
- 4. Conclusions



# **Why Evaluate Environmental Conditions**

- 1. Avoid Costly Mistakes
- 2. Protection of Sensitive Receptors
- 3. May render geothermal not feasible



# **Evaluating Environmental Conditions**

- 1. The type of ground exchanger (open, closed, standing column well) drives the study
- 2. Ask if there are existing environmental conditions
- 3. Review Existing Reports, if available
- 4. Review On-line Databases
- 5. Commercial Databases, like EDR (\$300)
- 6. Are there Environmental Issues at other sites in the area
- 7. Install Test Well to determine site geology
- 8. Examine Permitting Requirements-NPDES, UIC, Groundwater Discharge-May require water pre-testing and/or treatment
- 9. If soil or groundwater contamination, what is the extent.



# **Online Database Example**

3-0000723 QUINCY

#### MassDEP The Massachusetts Department of Environmental Protection New Search | Export to Excel | Definitions | Print Reportable Release Lookup View Map The search returned 459 results | Search Keywords >> 'QUINCY' | Sorted by: RTN | Data last updated: 03/25/2011 Reporting Notification Compliance RAO Chemical Supporting RTN City/Town Release Address Site Name/Location Aid Date Phase Status Class Type Documents Date Category 555 SOUTHERN ARTERY PHASE 3-0000005 QUINCY 10/16/1985 SUNOCO STATION NONE REMOPS 2/21/2011 RTE 3A PHASE 3-0000102 QUINCY 15 CENTER ST NONE 9/24/2007 TEXACO STATION 1/15/1987 TIER 2 <u>Files</u> II PHASE 3-0000117 QUINCY 728 SOUTHERN ARTERY OUINOIL TERMINAL NONE 1/15/1987 RAO 8/8/1997 Files IV NONE 4/15/1988 DPS 5/22/2003 3-0000128 QUINCY 1415-1439 HANCOCK ST ONE PARKINGWAY BLDG 3-0000144 QUINCY 15 LIBERTY ST AMOCO STATION NONE 1/15/1987 LSPNFA 3/10/1997 PHASE 11/20/2006 3-0000414 QUINCY 97-103 HOLMES ST ARCH GEAR FMR NONE 1/15/1987 RAO Oil <u>Files</u> IV 193-323 QUARRY ST QUINCY QUARRIES FMR 1/15/1987 RAO 6/4/2004 3-0000415 QUINCY NONE A3 YANKEE HEIGHTS 3-0000416 QUINCY RICCIUTI DR NONE 1/15/1987 TIER1D 8/9/1995 DEVELOPMENT 3-0000495 OUINCY CENTER ST CROWN COLONY PLACE NONE 1/15/1987 TIER1D 8/9/1995 PHASE 97 EAST HOWARD ST NONE RAO 4/30/2004 3-0000536 QUINCY GENERAL DYNAMICS FMR 1/15/1987 Files OFF 40 QUINCY AVE NONE 1/15/1987 RAO 5/16/1994 3-0000578 QUINCY BATES QUARRY FMR Oi1 EASTERN PEGGY PHASE 25 WEST HOWARD ST 3-0000628 QUINCY NONE 1/15/1990 RAO 3/22/1996 A2 ASSOCIATES TOWN RIVER BENT 3-0000639 QUINCY NONE 8/9/1996 BENT TER 1/15/1990 TIER1D TERRACE PHASE MATHEWSON 3-0000646 OUINCY 2 HANCOCK ST NONE 4/15/1988 TIER 2 2/22/2008 Files

CORPORATION

571 HANCOCK ST

AMOCO STATION FMR 127

NONE

7/15/1990

RAO




<u>Files</u>

IV PHASE


A2

Oil

6/13/1996









# **Open Loop**

- 1. Must have understanding of hydrogeology.
- 2. Effects on aquifer both extraction and injection.
- 3. Must have understanding of water chemistry.




#### **CASE STUDY**

- 1. City developing site as a community center
- 2. Existing building had a fuel oil leak from underground storage tank.
- 3. The site has on-going groundwater monitoring and an activity and use limitation.
- 4. Oil is present beneath existing building slab on water table.
- 5. Bedrock is present at surface at the site.
- 6. Design for new building includes geothermal heating and cooling using Standing Column Wells to 1500 feet. Water from wells discharge to storm drain.
- 7. An Environmental site evaluation for the geothermal design was not conducted.




# **CASE STUDY**





### **CASE STUDY**





# **What Happened**

- 1. Alares was hired as LSP to prepare a soil management plan for construction.
- 2. Alares reviewed construction documents to evaluate new foundation plan.
- 3. Noticed design drawings included standing column wells.
- 4. Asked if environmental assessment for wells was conducted.
- 5. No evaluation of site geology, permits, or environmental conditions had been conducted.
- 6. Construction Documents went out for public bid.
- 7. Geothermal designer added two additional Standing Column Wells for No-Bleed
- 8. Questions still unanswered concerning bedrock flow characteristics, i.e., installation of wells could worsen site conditions during well development.



# **What Happened**

- 1. Owner decided to change design to conventional HVAC system.
- 2. Costs for geothermal design approximately \$30k.
- 3. Owner now has negative view of geothermal.



#### **Conclusions**

- 1. Get environmental professional with geothermal experience involved early in the design.
- 2. Person conducting feasibility evaluation must have understanding the method of geothermal earth couples and how subsurface conditions could be affected.
- 3. Evaluate Permit requirements.
- 4. Environmental conditions can be managed.
- 5. Not all sites are appropriate for geothermal.

